



Layne Christensen Company
721 W. Illinois Avenue
Aurora, IL 60506

630/897-6941
graniteconstruction.com

October 20, 2018

Mr. Robert Leible
Assistant Superintendent of Water Production
City of Aurora
44 E. Downer Place
Aurora, IL 60507

Re: Well 127

Mr. Leible:

The Byron Jackson submersible pump was removed from Well 127 due to low cable/motor assembly electrical resistance. The flat cable motor link was found to be the problem. During this pump's last repair in 2010, the entire string of Line Pipe was replaced due to heavy corrosion. At that time, sacrificial anodes were installed on the pipe. The anodes were effective in that the pipe can be reused but it will require rethreading.

Please find Layne's Well 127 Pump Inspection Report attached. Total project estimate per the report's recommendations are as follows:

| | |
|--|-----------------|
| 1. Labor and equipment to date to remove pump; transport; disassemble, clean, and inspect components; televise well; Hi-Pot test cable | \$12,000 |
| 2. Service Byron Jackson motor, estimate | \$ 5,000 |
| 3. Rebuild bowl assembly, estimate | \$ 4,000 |
| 4. Rehabilitate Line Pipe including new zinc anodes, estimate | \$ 3,500 |
| 5. New flat cable motor link | \$ 6,000 |
| 6. Handle, transport, and install pump, test to waste, estimate | <u>\$ 9,000</u> |
| Total Project Estimate | \$39,500 |

I am attaching a new Schedule B. Our labor contract called for a 1 ½% increase on October 1.

As always, we welcome and encourage the City to visit our yard and inspect the pump components with us. Layne will proceed with the repairs and reinstallation upon the City's written notice to proceed. If you have any questions or comments, please do not hesitate to contact me.

Layne, a Granite Company

William Balluff, P.E.
Senior Project Manager

WORK ORDER



Layne, a Granite Company

721 W. Illinois Avenue, Aurora, IL 60506; Phone (630) 897-6941
 229 W. Indiana Ave., P.O. Box 489, Beecher, IL 60401; Phone (708) 946-2244

PROFESSIONAL SERVICES AGREEMENT
 SCHEDULE B

Purchaser: CITY OF AURORA, IL
 Job Location: WELL 127

SERVICE RATES - EFFECTIVE OCTOBER 1, 2018

| | Straight Time | | Overtime | Doubletime |
|--|---------------|-----------|----------|------------|
| | Per Hr. | 8 Hr. Day | Per Hr. | Per Hr. |
| Serviceman w/hand tools | 193.00 | 1544.00 | 289.50 | 386.00 |
| Serviceman w/service truck and hand tools, or welder | 222.00 | 1776.00 | 318.50 | 415.00 |
| Helper | 157.00 | 1256.00 | 235.50 | 314.00 |
| Serviceman and 1 Helper | 350.00 | 2800.00 | 525.00 | 700.00 |
| <u>Small Rig or Winch Truck (\$48.00)</u> | | | | |
| 1 Man Crew | 241.00 | 1928.00 | 337.50 | 434.00 |
| 2 Man Crew | 398.00 | 3184.00 | 573.00 | 748.00 |
| 3 Man Crew | 555.00 | 4440.00 | 808.50 | 1062.00 |
| <u>Middle Rig, Large Hoist or Flatbed Crane (\$64.00)</u> | | | | |
| 1 Man Crew | 257.00 | 2056.00 | 353.50 | 450.00 |
| 2 Man Crew | 414.00 | 3312.00 | 589.00 | 764.00 |
| 3 Man Crew | 571.00 | 4568.00 | 824.50 | 1078.00 |
| <u>Big Rig, Large Hoist and Poles, or Large Crane (\$105.00)</u> | | | | |
| 1 Man Crew | 298.00 | 2384.00 | 394.50 | 491.00 |
| 2 Man Crew | 455.00 | 3640.00 | 630.00 | 805.00 |
| 3 Man Crew | 612.00 | 4896.00 | 865.50 | 1119.00 |
| 4 Man Crew | 769.00 | 6152.00 | 1101.00 | 1433.00 |
| Power Tong Usage, per 8 hour shift | | 460.00 | | |
| <u>Machine Shop/Yard Labor and Equipment</u> | | | | |
| Machinist and Equipment | 187.00 | 1496.00 | 272.00 | 357.00 |
| 12" Threading Machine and Operator | 213.00 | 1704.00 | 298.00 | 383.00 |
| Serviceman w/hand tools | 170.00 | 1360.00 | 255.00 | 340.00 |
| Helper | 155.00 | 1240.00 | 232.50 | 310.00 |
| Sandblast Equipment and 2 man crew | 373.00 | 2984.00 | 535.50 | 698.00 |

Mileage: Auto: \$0.55 Pickup: \$0.70 1-Ton:\$1.00 2-1/2 Ton Flatbed: \$2.10 Semi-Tractor: \$2.75

Subsistence-Per Man

Over 55 miles radius from home office.....\$65.00 + Hotel

REMARKS:

SUBMITTED WITH REPAIR ESTIMATE OF 10/20/2018

Work Authorized on Behalf of Purchaser By: _____

Date: _____

Title: _____



721 WEST ILLINOIS AVE.
 AURORA, IL 60506
 630.897.6941 PHONE
 630.897.6976 FAX

CITY OF AURORA
 WELL NO. 127 PUMP
 INSPECTION REPORT

| | | | | | | |
|----------|--------|-----------------|--|-----|------|------------|
| JOB NAME | Aurora | | WELL NO. | 127 | DATE | 10/16/2018 |
| JOB NO. | 51161 | INSPECTED BY | J. Poppen, J. Kopp, J. Gilchrist, B. Balluff | | | |
| | | BOWL ASSEMBLY | Byron Jackson 3 stage 10MQH, all bronze | | | |
| | | COLUMN ASSEMBLY | 95' of 6" T&C Line Pipe, SRL | | | |
| | | MOTOR | Byron Jackson 40 HP, 10", 460V, Type H | | | |

MOTOR



Motor Observations

The motor megged 2700+ in the field and overload in the shop. Shaft projection, shaft rotation, and seal float meet specification. The exterior of the cans and the o-ring joint are in good condition. The balance tube is plugged with deposition. Reference attached Byron Jackson Motor Inspection – Type H

Motor Recommendations

Perform standard field motor service with balance line replacement and epoxy coat exterior.

BOWL ASSEMBLY



Bowl castings are in excellent condition with very little wear to internal clearances.

The stainless impeller shaft is heavily pitted.

The stainless collets are in very poor condition.

Bowl Assembly Observations

The wear ring clearances are well within new specification. Bushing clearances exceed tolerance. The stainless impeller shaft and collets exhibit heavy pitting and are in poor condition. It is an unusual circumstance that these stainless components are so heavily decayed. Stainless fasteners and suction strainer are in good condition. Reference attached Bowl Assembly Inspection Report.

Bowl Assembly Recommendations

Rebuild bowl assembly with new bushings, collets, and impeller shaft.

| | | |
|--|--|--|
| | | |
|--|--|--|



721 WEST ILLINOIS AVE.
 AURORA, IL 60506
 630.897.6941 PHONE
 630.897.6976 FAX

CITY OF AURORA
 WELL NO. 127 PUMP
 INSPECTION REPORT

COLUMN PIPE



6" Line Pipe on Layne blast rack.



Heavy iron deposition on pipe interior prior to sand blas (typ.)



Zinc sleeve sacrificial anodes appear to have abosorbed the brunt of corrossion.



However, the pipe still has some random pitting.



Interior pipe pit above sacrificial zinc anode.



Eroded thread on coupling.

Pipe Observations

After the entire string of 6" Line Pipe required replacement in 2010, sacrificial zinc anodes were installed on the new pipe. The anodes appear to be a good investment as they have taken the brunt of the corrosion in the last eight years of operation. However, all four single random joints do require thread removal and rethread (cut & thread). Three couplings and the surge control require replacement. The pitless guts and the pitless' threaded nipple are in good condition. The 6" x 5' stainless pup off the bowl is in good condition but its associated 6" Line Pipe coupling is in poor condition. The pipe string also includes 5' of 6" black steel with surge control valve.

Pipe Recommendations

Cut and thread four male ends. Replace three couplings and surge control. Plan a contingency to cut and thread two ends after removing the coupling/surge control – pending thread inspection at that time. Pending lost pipe length due to cut and thread, consider replacing 5" black steel nipple with new that compensates for the lost length. Install sacrificial zinc anodes.



721 WEST ILLINOIS AVE.
AURORA, IL 60506
630.897.6941 PHONE
630.897.6976 FAX

CITY OF AURORA
WELL NO. 127 PUMP
INSPECTION REPORT

CABLE – There is 6' of spare cable at the well head. The cable/motor assembly megged 0.4 at the well head and 0.3 with bowl/motor removed from well. The motor, without cable, megged 2700+. The cable and flat cable failed high potential testing. The #2 cable, without the flat cable motor link, passed high potential testing.

Cable Recommendation: Replace the flat cable motor link.

WELL – The well was televised on 10/08/2018. The formation has one area of fracturing and crevicing from 108' to 118'. The total depth was logged at 226'. This is the same TD televised in 2010. Bailing was attempted at that time with no return. Reference attached Downhole Video Survey Report.

BYRON JACKSON MOTOR INSPECTION - TYPE H

Inspected By J. Gilchrist Date 10/10/18

Job Name Aurora 127 Job # 51161W

HP 100 Size 10 Voltage 460

Motor Serial # No Tag

Meg OL-OL-OL

Shaft Projection Spec 6 5/8

Shaft Projection Measured 6 5/8

Rotation great

Float great

Condition of Stator Can good

Condition of Lower Can good

Condition of O-Ring Joint good

Condition of Balance Tube plugged

Balance Tube Clear? No

Comments Motor is in excellent condition with the exception of heavy deposition in the balance tube.

Is Motor Field Service Eligible? Yes

Recommendations: Perform standard field motor service with balance line replacement. Sandblast exterior and epoxy coat.



BOWL ASSEMBLY INSPECTION REPORT

| | | | | | | | |
|-----------------------|--|-----------------------|------------------|----------------------|-----------------------|------------------|------------|
| Project | | Aurora, IL | | Well No. | 127 | Date | 10/09/2018 |
| Project No. | | 51161 | | Inspected by | | Jeff | |
| Serial No. | | | | Bowl Assembly | | 10 MQH | |
| Stage No. | Wear Ring | Impeller Skirt | Clearance | Bearing ID | Impeller Shaft | Clearance | |
| 1 (suction) | 5.314 | 5.293 | .021" | 1.450 | 1.936 | .014" | |
| 2 | 5.315 | 5.293 | .022" | 1.450 | 1.936 | .014" | |
| 3 | 5.315 | 5.293 | .022" | 1.448 | 1.936 | .012" | |
| 4 | | | | 1.454 | 1.936 | .018" | |
| 5 | | | | | | | |
| 6 | | | | | | | |
| 7 | | | | | | | |
| 8 | | | | | | | |
| 9 | | | | | | | |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |
| 13 | | | | | | | |
| 14 | | | | | | | |
| 15 | | | | | | | |
| 16 | | | | | | | |
| 17 | | | | | | | |
| Impeller Shaft | 1 7/16 X 47 1/16 – Heavy pitting. Poor Condition | | | | | | |
| Fasteners | SST. - OK to reuse. | | | | | | |
| Strainer | SST. - OK to reuse. | | | | | | |
| Collets | Poor condition – should NOT be reused. | | | | | | |

COMMENTS: Impellers and pump casting in very good condition.

WATER RESOURCES



CABLE HIGH POTENTIAL TEST

Customer: Aurora, IL Date 10/03/2018 Job No 51161

Well No.: 127 Location: Aurora, IL -Layne Yard

Cable Description 600 Volt, #2 Length _____ Installed By _____
w/grnd..

Type of Test Proof Max. Test Voltage 2,000 Duration 5 min. Motor Voltage 460

Weather Indoors Temperature 80°F Humidity _____

Test Equipment 6 kV Test Set Test Engineer J. Geltz Time _____

READINGS ON VOLTAGE RISE

| Test Voltage | Leakage I in Micro - Amps | | |
|------------------------|---------------------------|----|----|
| | AØ | | CØ |
| | Red | | |
| 1st. | | | |
| 400 | 269.7 | UA | |
| 800 | .603 | MA | |
| 1200 | .979 | MA | |
| 1600 | 1.396 | Ma | |
| 2000 | 1.794 | MA | |
| 2nd | | | |
| 400 | 198.6 | UA | |
| 800 | .426 | MA | |
| 1200 | .607 | MA | |
| 1600 | .759 | MA | |
| 2000 | .916 | MA | |

READINGS WITH VOLTAGE CONSTANT

| Time in Min. | Leakage I in Micro - Amps | | |
|--------------|---------------------------|----|----|
| | AØ | | CØ |
| | Red | | |
| | | | |
| 0 | 1.974 | MA | |
| 1 | 1.299 | MA | |
| 2 | 1.006 | MA | |
| 3 | .820 | MA | |
| 4 | .698 | MA | |
| 5 | .600 | MA | |
| | | | |
| 0 | .916 | MA | |
| 1 | .610 | MA | |
| 2 | .496 | MA | |
| 3 | .424 | MA | |
| 4 | .371 | MA | |
| 5 | .333 | MA | |

DISCHARGE TIME

Comments:

Cable tested with Byron Jackson flat cable attached. FAIL

Witness:

Signature:

_____ John Geltz

WATER RESOURCES



CABLE HIGH POTENTIAL TEST

Customer: Aurora, IL Date 10/03/2018 Job No 501161

Well No.: 127 Location: Aurora, IL – Layne Yard

Cable Description 600 Volt, #2 w/grnd. Length 100' + or - Installed By _____

Type of Test Proof Max. Test Voltage 2,000 Duration 5 min. Motor Voltage 460

Weather Indoors Temperature 80°F Humidity _____

Test Equipment 6 kV Test Set Test Engineer J. Geltz Time _____

READINGS ON VOLTAGE RISE

| Test Voltage | Leakage I in Micro - Amps | | |
|--------------|---------------------------|-------|--------|
| | AØ | BØ | CØ |
| | Red | Brown | Yellow |
| 400 | 1.6 | 1.3 | 1.2 |
| 800 | 1.5 | 1.4 | 1.3 |
| 1200 | .9 | 1.6 | 1.4 |
| 1600 | 1.3 | 1.4 | 1.6 |
| 2000 | 1.5 | 1.5 | 1.6 |
| | | | |
| | | | |
| | | | |

READINGS WITH VOLTAGE CONSTANT

| Time in Min. | Leakage I in Micro - Amps | | |
|--------------|---------------------------|-------|--------|
| | AØ | BØ | CØ |
| | Red | Brown | Yellow |
| 0 | 1.5 | 1.5 | 1.6 |
| 1 | .5 | .2 | .5 |
| 2 | .4 | .4 | .2 |
| 3 | .4 | .4 | .4 |
| 4 | .3 | .3 | .3 |
| 5 | .5 | .4 | .4 |
| | | | |
| | | | |
| | | | |

DISCHARGE TIME

Comments:

Hypot test Power Cable only w/NO B.J. flat cable attached. B.J. Flat-cable = 15' long. Leakage values are low.
 Cable appears suitable for reuse.
 Note that reinstallation means cable as tested on spool above ground will be flexed over cable sheaves, squeezed against pipe by stainless steel banding and will be subject to possible down-hole damage, as well as significant hydrostatic pressure.
 Hypot testing may not detect leakage to atmosphere (i.e. external holes in cable insulation).

Witness:

Signature:

 John Geltz

WATER RESOURCES



DOWNHOLE VIDEO SURVEY REPORT

Date 10/08/2018

Client: City of Aurora, IL

Project Number: 51161 Well No: 127 S.W.L. 18' 6"


Location: 1048 Almond Drive

County: Kane City: Aurora State: IL

Sec: 8 Twp: 38N Range: 8E

Flash Drive Made: Yes No Well Back flushed no

Driller's Report: 24" cemented casing to 47', 19" open lime hole to 240' TD

| Depth | | Description |
|--------|-------------------|---|
| | | All measurements from top of pitless at 26" above grade. |
| | Pitless discharge |  |
| 18' 6" | | Static water level |

WATER RESOURCES



A GRANITE COMPANY


DOWNHOLE VIDEO SURVEY REPORT

18' 6"

46'

Moderate
scale on well
casing.

Aurora #127 10/8/18
0041.4F
10/08/18



WATER RESOURCES

721 W. Illinois Avenue; Aurora, IL 60506 | Office: 630-897-6941 | Fax: 630-897-6976 | layne.com



A GRANITE COMPANY

DOWNHOLE VIDEO SURVEY REPORT

46'

Bottom of casing.



WATER RESOURCES


721 W. Illinois Avenue; Aurora, IL 60506 | Office: 630-897-6941 | Fax: 630-897-6976 | layne.com



A GRANITE COMPANY

DOWNHOLE VIDEO SURVEY REPORT

"Stalactites"
hanging from
bottom of
casing




WATER RESOURCES

721 W. Illinois Avenue; Aurora, IL 60506 | Office: 630-897-6941 | Fax: 630-897-6976 | layne.com



A GRANITE COMPANY

DOWNHOLE VIDEO SURVEY REPORT

| | | |
|-----|--|---|
| 108 | 118 The only significant fractures and crevicing in well's open limestone formation |  <p>Aurora #127 10/8/18 0115.9F 10/08/18</p> The image shows a downhole video survey of a wellbore. A central tool joint is visible, surrounded by a dark, textured limestone formation. The formation exhibits numerous small, bright, reflective particles and irregularities, indicating fractures and crevices. The lighting is focused on the tool joint, creating a bright circular highlight. |
|-----|--|---|

WATER RESOURCES



DOWNHOLE VIDEO SURVEY REPORT

| | | |
|-----|--------------------------|---|
| 118 | 226 Smooth bore hole. | |
| | 226' | Total depth – the same total depth logged during 2010 pump repair. At that time, attempts were made to bail material with no return and no increase in total depth. |
| | | |
| | | |
| | | |
| | | |

| | | | |
|------------------------|-----------------------|--------------------------|-----------------------|
| Technician | John Geltz | Account Manager | Michael McDonald |
| Project Manager | William Balluff, P.E. | Operations Review | William Balluff, P.E. |

WATER RESOURCES