






*Path over Structure*



*Elevation View*



*Typical Steel Deterioration*



*Pack Rust and Section Loss in Stringer*



*Pack Rust at Weld Between Picket and Tube*



*Bridge Underside*