



435 West Fullerton Ave  
Elmhurst, IL 60126-1404  
Office # (630) 279-7171  
Fax # (630) 279-7676  
www.AdventSystems.com

# QUOTATION

October 1, 2015

AS65867-R2

---

**To:** City of Aurora  
44 E. Downer Place  
P.O. Box 2067  
Aurora, IL 60507

**Project:** Aurora Lincoln Lot Install New cameras. 9-28-15

**Attn:** Purchasing Div of Finance Dept

**Phone:** (630) 256-3550

---

Prices are for equipment and services as listed only, unless otherwise specified herein. Any alteration or deviation involving extra costs will be executed only upon written order and will become an extra charge over and above this quotation. Because of conditions beyond our control, this quotation is effective only for a period of THIRTY DAYS from the date above. Taxes now in effect or if and when levied on any sale based on this quotation must be added to the price, unless specifically provided for in the quotation. Deliveries are subject to all causes beyond our control, or whatever nature, and also in addition subject to strikes, accidents, and failure of raw material supplies.

**TERMS - THIRTY DAYS NET FROM DATE OF INVOICE. ALL QUOTATIONS IN U.S. DOLLARS UNLESS OTHERWISE NOTED.** No cash discounts for prepayment. Any order based on this quotation shall be subject to approval and acceptance by Advent Systems, Inc.

---

We are pleased to submit the following quotation on the above mentioned project.

## Lincoln Lot 10 Cameras and Point to Point Wireless System

### **Qty Description**

10	Genetec Omnicast Professional Single Camera Connection
8	Axis P1427-LE - 5 Bullet Megapixel Network Camera with IR LED
2	Axis M3025-VE Mini-Dome Camera
3	Locking Nema Enclosure
3	Comnet Hardened Wireless Ethernet Device KIT NWK9
3	Comnet Hardened 5 Port 1000Mbps Managed Switch , 2 TX/FX (SFP) Combo, 3 10/100/1000Mbps TX Ports, Includes Power Supply
1	Miscellaneous Mounting Parts
3	2" Aluminum Rigid Conduit 10'
2	Protective cover for Tunnel Cameras
2	Axis T91A47 POLE MOUNT 60-110MM
1	Lot of Wire

**Section Total** **\$30,725.00**

## 2nd Man OSHA Required for Lift Safety

### **Qty Description**

48	2nd man for Lift Safety While Operatinig
----	--

**Section Total** **\$2,843.00**



435 West Fullerton Ave  
Elmhurst, IL 60126-1404  
Office # (630) 279-7171  
Fax # (630) 279-7676  
[www.AdventSystems.com](http://www.AdventSystems.com)

## QUOTATION

October 1, 2015

AS65867-R2

### Qualifications

- This Quotation assumes all existing equipment is in good working condition. Repairs to existing equipment is at additional cost.
- All work will be performed during normal working hours
- Please note: Installations of this type may be disruptive to your day to day operations. Advent Systems will coordinate and do everything possible to minimize this disruption.
- Above includes freight and a one-year warranty on parts and labor excluding "In Box Sale" items.
- A lift/Bucket truck is required for this project. This is not included in this quote. Per our conversation, the City of Aurora will supply one. Advent Systems can supply both if needed. This would be an additional cost.
- This quote does not include the cost of a Flagger or Additional insurance. This would require a change order if required.
- This quote does not include conduit or conduit back boxes to the camera mounting location from the ground level. And the camera(s) located in the tunnel walkway to the transmitter location to be determined.
- We are not including any insurance for working near the tracks. I do not believe at these distances it would be required.
- Per OSHA Regulations, we need to provide a spotter while any lift work is being done. This has to be an Advent employee. This is included in this quote.
- The receiver located at the head end location will be installed by Owner. A network connection from the RT25 head-end will be required at the receiver. This is not included in the quote. A final determination of mounting point will need further investigation.

Accepted by: \_\_\_\_\_

Title: \_\_\_\_\_

Date: \_\_\_\_\_

\_\_\_\_\_  
Dave Czyzewicz  
630-532-5256  
[davec@adventsystems.com](mailto:davec@adventsystems.com)