



Pictures of Liberty Street Nuisance Flows

Ice Caused by Groundwater at 2375 Liberty St Looking East

Ice Caused by Groundwater at 2375 Liberty St Looking South







Engineer's Estimate Liberty Street Storm Sewer Extension

Route County Local Agency Liberty Street

DuPage

City of Aurora

<u>NO.</u>	<u>ITEM</u>	<u>UNIT</u>	QUANTITY	UNIT COST	<u>AMOUNT</u>
1	Select Granular Trench Backfill	CY	55	\$25.00	\$1,375.00
2	Storm Sewer - 12" DIP	LF	215	\$100.00	\$21,500.00
3	Infiltration Catch Basin, 3' dia.	EA	1	\$5,000.00	\$5,000.00
4	Modify Existing Structure	EA	3	\$750.00	\$2,250.00
5	Class D Patching, 10" Binder & 1.5" Surface	SY	100	\$95.00	\$9,500.00
6	PCC Driveway Removal and Replacement, 8"	SY	45	\$100.00	\$4,500.00
7	Sidewalk Removal and Replacement, 5"	SF	75	\$8.00	\$600.00
8	Combination PCC Curb and Gutter Removal and Replacement	LF	215	\$40.00	\$8,600.00
Engineer's Estimate for Making Entire Improvements =					\$53,325.00
10% Contingency =					\$5,332.50
Total Estimate =					\$58,657.50