



Spruce St (Looking Southeast)



Pavement Heaving around Bank Driveway (Looking North)



Pavement Heaving (Looking South)



Rough Pavement from Watermain Break (Looking South)



Damage at Bank Driveway (Looking Northwest)