



435 West Fullerton Ave  
Elmhurst, IL 60126-1404  
Office # (630) 279-7171  
Fax # (630) 279-7676  
www.AdventSystems.com

## QUOTATION

Jun 30, 2017

AS71543-R1

---

**To:** Phillips Park Golf Course / City of Aurora  
1001 Hill Avenue  
Aurora, IL 60505

**Project:** Phillips Park Golf Course  
CCTV Surveillance System Replacement & Upgrade

**Attn:** Jeff Schmidt

**Phone:** (630) 256-3760

**Email:** jschmidt@aurora-il.org

---

Prices are for equipment and services as listed only, unless otherwise specified herein. Any alteration or deviation involving extra costs will be executed only upon written order and will become an extra charge over and above this quotation. Because of conditions beyond our control, this quotation is effective only for a period of THIRTY DAYS from the date above. Taxes now in effect or if and when levied on any sale based on this quotation must be added to the price, unless specifically provided for in the quotation. Deliveries are subject to all causes beyond our control, or whatever nature, and also in addition subject to strikes, accidents, and failure of raw material supplies.

**TERMS - THIRTY DAYS NET FROM DATE OF INVOICE. ALL QUOTATIONS IN U.S. DOLLARS UNLESS OTHERWISE NOTED.** No cash discounts for prepayment. Any order based on this quotation shall be subject to approval and acceptance by Advent Systems, Inc.

---

We are pleased to submit the following quotation on the above mentioned project.

### **Scope of Work**

Camera replacement, upgrade and expansion for the Phillips Park Golf Course City Hall.

#### **Qty Description**

- 1 GENETEC LICENSING & SOFTWARE:  
(Server and Genetec license that the cameras will be connected to is to be determined.)
- 1 Genetec single client software
- 8 Genetec camera connection
- 1 Genetec™ Advantage for 1 Omnicast Camera – Prorated to expire with the balance of the system on September 30, 2019
- 1 INTERIOR CAMERA LOCATIONS:
- 4 Axis P3225-LV IP camera
- 4 Axis P3225 recessed mounting kit
- 4 Quam plenum rated top hat
- 1 EXTERIOR GOLF CART PATH STORAGE AREA:
- 1 Axis P1435 Bullet style IP cameras (10-22mm)
- 1 Junction box mounting ring
- 1 Mounting junction box
- 1 Lot-Safety technician-OSHA  
(Boom truck.)
- 1 Note:  
(The existing camera will be removed. The new camera will be installed under the soffit area. The existing roof mounted bracket will remain in place for future removal.)
- 1 EXTERIOR PARKING LOT:  
(The exterior parking lot is very large. In order to provide proper coverage it is recommended that three IP cameras be installed each viewing a segment of the parking lot.)
- 3 Axis P1435 Bullet style IP cameras (10-22mm)
- 3 Junction box mounting ring
- 3 Mounting junction box
- 1 MISCELANOUS:
- 8 Cat6 Mod Plugs
- 8 RJ45 Connectors
- 9 Point of connection to the City of Aurora provided network drop



435 West Fullerton Ave  
Elmhurst, IL 60126-1404  
Office # (630) 279-7171  
Fax # (630) 279-7676  
www.AdventSystems.com

## QUOTATION

Jun 30, 2017

AS71543-R1

Qty	Description
-----	-------------

1	PoE Switch (A new security 24 port PoE switch will be installed. Location is to be determined.)
4	Lot-Core-sleeve and seal
1	Lot of Wire

**Total Base System Investment**

**\$20,030.00**

**Option One-18th Fairway**

Install an exterior IP camera providing a general view of the 18th fairway near the club house.

Qty	Description
-----	-------------

1	GENETEC LICENSING & SOFTWARE: (Server and Genetec license that the cameras will be connected to is to be determined.)
1	Genetec camera connection
1	Genetec™ Advantage for 1 Omnicast Camera – Expires September 30 2019
1	18TH FAIRWAY:
1	Axis P1435 Bullet style IP cameras (10-22mm
1	Junction box mounting ring
1	Mounting junction box
1	MISCELANOUS:
1	Cat6 Mod Plugs
1	RJ45 Connectors
1	Point of connection to the City of Aurora provided network drop
1	Lot-Core, sleeve and seal

**Total Add To The Above Listed Base System Investment For Option One**

**\$2,235.00**

**Option Two-Maintenance Shed**

Install an exterior IP camera providing a general view of the front entrance doors on the maintenance shed.

Qty	Description
-----	-------------

1	GENETEC LICENSING & SOFTWARE: (Server and Genetec license that the cameras will be connected to is to be determined.)
1	Genetec camera connection
1	Genetec™ Advantage for 1 Omnicast Camera – Expires September 30 2019
1	MAINTENANCE SHED:
1	Axis P1435 Bullet style IP cameras (10-22mm
1	Junction box mounting ring
1	Mounting junction box
1	MISCELANOUS:
1	Cat6 Mod Plugs
1	RJ45 Connectors
1	Point of connection to the City of Aurora provided network drop (In the maintenance shed.)



435 West Fullerton Ave  
Elmhurst, IL 60126-1404  
Office # (630) 279-7171  
Fax # (630) 279-7676  
[www.AdventSystems.com](http://www.AdventSystems.com)

## QUOTATION

Jun 30, 2017

AS71543-R1

Qty	Description
-----	-------------

1	PoE Switch (A new security 8 port PoE switch will be installed. Location is to be determined.)
1	Lot-Core, sleeve and seal
100	3/4" Conduit
1	Lot-Miscellaneous exterior junction boxes
1	A Card differential

**Total Add To The Above Listed Base System Investment For Option Two**

**\$4,699.00**

### Qualifications

- All work will be performed during normal working hours
- Conduit, Conduit whips, conduit stubs, riser, coring, junction boxes and 120VAC 20-amp circuit furnished and installed by others.
- Network connectivity with static IP addresses including subnet and gateway as required furnished by others.
- Please note: Installations of this type may be disruptive to your day to day operations. Advent Systems will coordinate and do everything possible to minimize this disruption.
- Taxes have been excluded
- The above listed option pricing is based on all work being done concurrent with the base system.
- Above includes freight and a one-year warranty on parts and labor.

Accepted by: \_\_\_\_\_

Title: \_\_\_\_\_

Date: \_\_\_\_\_

Richard M. Ruszkowski  
Senior Account Executive  
(630) 532-5231

[rich\\_r@adventsystems.com](mailto:rich_r@adventsystems.com)