



City of Aurora, IL
Engineering

Jason Bauer, Director of Public Works/City Engineer
 44 E Downer Place, Aurora, IL 60502

EVALUATION TABULATION

ITB No. 26-017

2026 Manhole Rehabilitation

RESPONSE DEADLINE: March 11, 2026 at 11:00 am

Report Generated: Thursday, March 12, 2026

SELECTED VENDOR TOTALS

Vendor	Total
Structured Solutions, LLC	\$379,690.00
National Power Rodding Corp.	\$399,810.00
KIM Construction Co.Inc	\$404,675.00
Hoerr Construction, Inc.	\$489,514.00
Visu Sewer Inc	\$550,010.00
Insituform	\$617,433.00

SCHEDULE OF PRICES (Table 1 of 2)

Schedule of Prices					Hoerr Construction, Inc.		Insituform		KIM Construction Co.Inc		National Power Rodding Corp.		Structured Solutions, LLC	
Selected	Line Item	Description	Quantity	Unit of Measure	Unit Cost	Total	Unit Cost	Total	Unit Cost	Total	Unit Cost	Total	Unit Cost	Total
X	1	Curtain Grout Bottom 18" - Sanitary	12	EACH	\$1,405.00	\$16,860.00	\$1,735.00	\$20,820.00	\$580.00	\$6,960.00	\$800.00	\$9,600.00	\$1,800.00	\$21,600.00

EVALUATION TABULATION
ITB No. 26-017
2026 Manhole Rehabilitation

Schedule of Prices					Hoerr Construction, Inc.		Insituform		KIM Construction Co.Inc		National Power Rodding Corp.		Structured Solutions, LLC	
Selected	Line Item	Description	Quantity	Unit of Measure	Unit Cost	Total	Unit Cost	Total	Unit Cost	Total	Unit Cost	Total	Unit Cost	Total
X	2	Remove and Replace Manhole Bench - Sanitary	23	EACH	\$2,620.00	\$60,260.00	\$2,225.00	\$51,175.00	\$2,300.00	\$52,900.00	\$600.00	\$13,800.00	\$1,850.00	\$42,550.00
X	3	Grout Cone/Corbel - Sanitary	1	EACH	\$1,412.00	\$1,412.00	\$1,215.00	\$1,215.00	\$850.00	\$850.00	\$1,500.00	\$1,500.00	\$1,500.00	\$1,500.00
X	4	Full Curtain Grout - Sanitary	4	EACH	\$1,936.00	\$7,744.00	\$4,235.00	\$16,940.00	\$1,300.00	\$5,200.00	\$2,000.00	\$8,000.00	\$3,200.00	\$12,800.00
X	5	Cement Lining of Interior Walls - Sanitary	755	VERTICAL FOOT	\$305.00	\$230,275.00	\$495.80	\$374,329.00	\$293.00	\$221,215.00	\$275.00	\$207,625.00	\$272.00	\$205,360.00
X	6	Grout Wall Joints - Sanitary	8	EACH	\$1,700.00	\$13,600.00	\$1,400.00	\$11,200.00	\$550.00	\$4,400.00	\$500.00	\$4,000.00	\$450.00	\$3,600.00
X	7	Chimney Rehabilitation, Non-Pavement - Sanitary	12	EACH	\$5,400.00	\$64,800.00	\$2,950.00	\$35,400.00	\$2,500.00	\$30,000.00	\$5,700.00	\$68,400.00	\$2,200.00	\$26,400.00
X	8	Chimney Rehabilitation, Pavement - Sanitary	4	EACH	\$6,400.00	\$25,600.00	\$9,225.00	\$36,900.00	\$3,400.00	\$13,600.00	\$6,840.00	\$27,360.00	\$3,200.00	\$12,800.00
X	9	Fill In Structure Void	10	EACH	\$1,395.00	\$13,950.00	\$560.00	\$5,600.00	\$300.00	\$3,000.00	\$650.00	\$6,500.00	\$400.00	\$4,000.00

EVALUATION TABULATION
 ITB No. 26-017
 2026 Manhole Rehabilitation

Schedule of Prices					Hoerr Construction, Inc.		Insituform		KIM Construction Co.Inc		National Power Rodding Corp.		Structured Solutions, LLC	
Selected	Line Item	Description	Quantity	Unit of Measure	Unit Cost	Total	Unit Cost	Total	Unit Cost	Total	Unit Cost	Total	Unit Cost	Total
X	10	Grout 48" Elliptical Pipe Joint - Sanitary	2	EACH	\$2,554.00	\$5,108.00	\$5,180.00	\$10,360.00	\$8,000.00	\$16,000.00	\$2,500.00	\$5,000.00	\$650.00	\$1,300.00
X	11	Remove and Replace Manhole Bench - Storm	2	EACH	\$2,440.00	\$4,880.00	\$2,322.00	\$4,644.00	\$2,800.00	\$5,600.00	\$1,950.00	\$3,900.00	\$1,850.00	\$3,700.00
X	12	Cement Lining of Interior Walls - Storm	15	VERTICAL FOOT	\$335.00	\$5,025.00	\$590.00	\$8,850.00	\$330.00	\$4,950.00	\$275.00	\$4,125.00	\$272.00	\$4,080.00
Total						\$449,514.00	\$577,433.00	\$364,675.00	\$359,810.00	\$339,690.00				

SCHEDULE OF PRICES (Table 2 of 2)

Schedule of Prices					Visu Sewer Inc	
Selected	Line Item	Description	Quantity	Unit of Measure	Unit Cost	Total
X	1	Curtain Grout Bottom 18" - Sanitary	12	EACH	\$1,115.00	\$13,380.00
X	2	Remove and Replace Manhole Bench - Sanitary	23	EACH	\$5,000.00	\$115,000.00
X	3	Grout Cone/Corbel - Sanitary	1	EACH	\$1,485.00	\$1,485.00
X	4	Full Curtain Grout - Sanitary	4	EACH	\$1,690.00	\$6,760.00
X	5	Cement Lining of Interior Walls - Sanitary	755	VERTICAL FOOT	\$330.00	\$249,150.00

EVALUATION TABULATION
 ITB No. 26-017
 2026 Manhole Rehabilitation

Selected	Line Item	Schedule of Prices			Visu Sewer Inc	
		Description	Quantity	Unit of Measure	Unit Cost	Total
X	6	Grout Wall Joints - Sanitary	8	EACH	\$970.00	\$7,760.00
X	7	Chimney Rehabilitation, Non-Pavement - Sanitary	12	EACH	\$2,700.00	\$32,400.00
X	8	Chimney Rehabilitation, Pavement - Sanitary	4	EACH	\$8,500.00	\$34,000.00
X	9	Fill In Structure Void	10	EACH	\$3,000.00	\$30,000.00
X	10	Grout 48" Elliptical Pipe Joint - Sanitary	2	EACH	\$1,650.00	\$3,300.00
X	11	Remove and Replace Manhole Bench - Storm	2	EACH	\$5,200.00	\$10,400.00
X	12	Cement Lining of Interior Walls - Storm	15	VERTICAL FOOT	\$425.00	\$6,375.00
Total						\$510,010.00

ITEMS ORDERED BY ENGINEER

Items Ordered by Engineer				Hoerr Construction, Inc.	Insituform	KIM Construction Co.Inc	National Power Rodding Corp.	Structured Solutions, LLC	Visu Sewer Inc
Selected	Line Item	Description	Unit of Measure	Unit Cost	Unit Cost	Unit Cost	Unit Cost	Unit Cost	Unit Cost
X	13	Items Ordered by Engineer	ALLOWANCE	\$40,000.00	\$40,000.00	\$40,000.00	\$40,000.00	\$40,000.00	\$40,000.00
Total				\$40,000.00	\$40,000.00	\$40,000.00	\$40,000.00	\$40,000.00	\$40,000.00

VENDOR QUESTIONNAIRE PASS/FAIL

EVALUATION TABULATION
 ITB No. 26-017
 2026 Manhole Rehabilitation

Question Title	Hoerr Construction, Inc.	Insituform	KIM Construction Co.Inc	National Power Rodding Corp.	Structured Solutions, LLC	Visu Sewer Inc
Bid Deposit	Pass	Pass	Pass	Pass	Pass	Pass
Contact Information	Pass	Pass	Pass	Pass	Pass	Pass
References	Pass	Pass	Pass	Pass	Pass	Pass
Eligibility	Pass	Pass	Pass	Pass	Pass	Pass
Bidder's Tax Certification	Pass	Pass	Pass	Pass	Pass	Pass
Bidder's Certification	Pass	Pass	Pass	Pass	Pass	Pass
Apprenticeship or Training Program Certification	Pass	Fail	Pass	Pass	Pass	Pass
Union/Apprenticeship Requested Documentation	Pass	Fail	Pass	Pass	Pass	Pass
Standard City of Aurora Contract	Pass	Fail	Pass	Pass	Pass	Pass
Additional Information	Pass	No Response	Pass	Pass	Pass	Pass