





Front, lower -




Front

Front middle
upper

Front upper

Back of house



Back lower





Back
right side







Back
upper




Front
upper





15 ropes broke
All remaining
ropes weak &
deteriorating





Photos taken by Planning & Zoning